



These two points must be soldered for transform into CB 400 Ch